


24

24



18

12

6

6

40

35

30

25

20

15

10

5

0

40

35

30

25

20

15

10

5

0

40

35

30

25

20

15

10

5

0

24

40
35
30
25
20
15
10
5
0

24

30

35

40

40
35
30
25
20
15
10
5
0

12

30

35

40

40
35
30
25
20
15
10
5
0


6


30

35

40

24





24

18

12

6

24

0

5

10

15

20

25

30

35

40

0

5

10

15

20

25

30

35

40

Come off.

24

Turbidity blue out

No response on Tide, Wind, D.O.,
Cond. Temp.

20

15

10

5

0

18

35

30

25

20

15

10

5

0



35

30

25

20

15

10

5

0

12

40

35

30

25

20

15

10

5

0

6

40

35

30

25

20

15

10

5

0

24

Sept. 68

35
30

Sept. 5, 1968
1003

25
20
15
10
5
0

Pump off & ink pads had
come off.



no good
no bulb


35
30
25
20
15
10
5
0

18




5 Sept. 68

NO parameter printing correctly
NO response in span or zero set.



- 1 - T R
- 2 - T Black
- 3 - C Brown
- 4 - Tm - G
- 5 - Tm - Purple
- 6 - W - Brown
- 7 - D.O - Blue
- 8 - W - Blue

35





Sept. 6, 1968
 Replaced bulb in ~~the~~ Turbidity sensor

Replaced 2 12AV7 Tubes in amplifier - didn't change response

attempted to turn clock wise amplifier gain - non left gain clear up + turn gain back, after this

29 Sept. 68
10



10 Sept. 68

all parameters readily sent upon
except wind direction and turbidity

40 35 30 25 20 15 10 5 0

24

24

40
35
30
25
20
15
10
5
0

35

30

25

20

15

10

5

0

18

40
35
30
25
20
15
10
5
0

35

30

25

20


15

10

5

0

12



40
35
30
25
20
15
10
5
0

35

30

25

20

15

10

5

0

6

24

24

18

20

15

10

5

0

35

30

25

R

12

20

15

10

5

0

35

30

25

6

24

40

40

24

40 35 30 25 20 15 10 5 0

18

13

12

40 35 30 25 20 15 10 5 0

6

40 35 30 25 20 15 10 5 0

24

24

20

35

30

25

15

10

5

0

40

18

20

35

30

25

15

10

5

0

40

12

III

20

35

30

25

15

10

5

0

40

6

24

5

40
35
30
25
20
15
10
5
0

18

12

40
35
30
25
20
15
10
5
0

6

24

24

40 35 30 25 20 15 10 5 0

18

9

40 35 30 25 20 15 10 5 0

12

40 35 30 25 20 15 10 5 0


24


12:15 the pump went off

the pump reset motor shorting & capacitor ~~then~~ seems to be over heated mostly one of the leads possibly shorted or at least the neutral was coming off.

and come upon 240V

replaced ~~with~~ capacity






Sept. 18, 1968 @ 1030


Not printing of pump

next D.D. + 1.0 ppm


pump started after putting off. power omitted
 off and then turning power omitted back on.
 All power omitted


1715 the osm meter






20








Cond 2nd check @ 20:38

rest²⁰ Turbidity¹⁰ - 23


rest D.D. - .8
 before cleaning 5.4
 after 6.5
 f: 9

cleanshaft rotor on wind vanes
 vel & direction


23




25




26






28



25



30 Sept. 68

