






1 April 68





























10 April


10 April 68


Patuxent River Bridge and




















HW T 24

Surf. temp - 75.7 / 75.7
--- 100 ft mark ---

Cond 15.5
3MCl 35.8

DO 9.2 / 9.0

Tide 2.0 / 1.6

air temp 30 / 30
rel 50 / 50

Turb


Δ

above 36.0

Roast - tide

#

-4 ft





51


Rest time + $1\frac{1}{4}$ hrs
19 April 68

Surf. temp - 19517/1957


H.W.









22







24





25




26









April 30

soil now OK
put in trash barrel
and gave clorex
treat ment

