





6911 NR


replaced D.O. cell



























10










13













17










20







Jan 22 Jan, 69











26














Month	Day	Time	Surf. Temp.	Bottom Temp.	Conductivity	Dissolved Oxygen	Turb.	Tide	Wind Dir.	Wind Vel.	Notes
Jan	1969	1415	1.5	1.5	24.9	10.6	25	+0.4	SW	20	Reset Bot Temp. +1°C
Jan	11	1355	1.5	1.3	24.9 8°C	9.6	21	-0.7	NW	8	D.O. Not working properly needs to be reset
Jan	22	0945	2.6	2.6	23.1	10.5	before 63 after 35	+1.0	NW	16	Turbidity glass was dirty Reset and +700
					23.8 6°C		18 23	+0.8	N	16	reset timer + 25 min